

# **Last dandelion of the year**

---



# Corner dentil completed

---



**“J.C.” rests on my jacket in the sun**

---





# Another corner completed

---



# The production line

---



# **“Buffy” sneaks over for a visit**

---



# Stepping down the gable end

---





# Gable end half completed

---






**I always sign my work - Ken**

---



# Cover it for posterity

---



# Location – above the front door

---



**4 brads and it's attached**

---





# Alongside is “The Crew”

---



# **It's way up there**

---



# **Directly above the entrance**

---



# **Dentil across the front completed**

---





# Steve combining corn

---



# Gable end is finished

---



# June & “Buffy” – the dentil painters

---



# Ken, Dave & J.C. have lunch

---





# Window casings to finish

---



# Move to the north end gable

---



**The original bricklayer was drunk  
or had dropped his level!**

---





**This one's better**

---





# Trimming out the window

---



# **Dave puts on the final touches**

---



# The girl's carved pumpkins

---





# Caught on camera

---





# **A resting place for the brad gun**

---




**Curtis: Harry missed two joints!**

---



**Don't worry Curtis, it's fixed.**

---



# **Dentil completed on north gable**

---





# **“J.C.” on my jacket again**

---



# Finishing the window trim

---



# Walnut brackets on the porch post

---



# Half a heart

---





# Brackets installed, rain starts

---



**Monday November 10, 2008 – snow!**

---



# Trimming a bedroom window

---



# First the sill is installed

---





# Jamb extensions, top and side panel installed

---



# **“J.C” inspects and approves**

---



**One more side, then the casings – These came from an 1860 stone house**

---

